

# Powermax1650 Increases Productivity

- Significantly faster cut speeds (as much as 5 times faster depending on thickness)
- Significantly faster pierce time
- Less rework due to better cut quality
- No preheating required

	<b>¼" (6 mm)</b>	<b>½" (12 mm)</b>	<b>¾" (20 mm)</b>	<b>1" (25 mm)</b>
<b>Oxyfuel</b>	26 ipm	20 ipm	17 ipm	14 ipm
<b>Powermax1650 (100 amp)</b>	135 ipm	57 ipm	26 ipm	18 ipm
<b>% Increase in Speed</b>	<b>5 times faster</b>	<b>2.85 times faster</b>	<b>1.5 times faster</b>	<b>1.28 times faster</b>

Speeds are optimum speeds from cut charts.

# Increased Productivity Equation for 1/2"

Linear feet cut = **Duration** of time x **Speed** ÷ 12 (to convert inches to feet)

## PLASMA

**Duration** = 60 minutes  
**Speed** = 57 ipm (1/2")

$$(48^* \times 57) \div 12 = 228$$

## OXYFUEL

**Duration** = 60 minutes  
**Speed** = 20 ipm (1/2")

$$(60 \times 20) \div 12 = 100$$


### ASSUMPTIONS:

**Duration** = assume 60 minutes for this example

**Speed** = inches per minute, optimum speed per cut charts

*\*Example chosen using Powermax1650 at 80% duty cycle, which means it can cut 48 minutes out of 60. We are not taking into account pre-heat time for oxyfuel, pierce delay, and secondary operations. All of these factors, if taken into account, would further decrease the amount produced by oxyfuel.*

# Increased Productivity



Based on an 80% duty cycle for the Powermax1650.